

## The Information of Daniao Station

In 2009, the extremely heavy rain of typhoon Morakot caused the potential debris flow torrent upstream large-scale landslide in Daniao tribe, large amount of stones poured down from the mountain, burying downstream buildings and causing subgrade loss. In order to pre-warn the occurrence of debris flow, Soil and Water Conservation Bureau completed the construction of the Daniao station in Daniao Village, Dawu Township, Taitung County in 2010 (The potential debris flow torrent number, Taitung County DF097).

<b>The information of station</b>		Last updated : 2023/06/30	
<b>District</b>	Daniao Village, Dawu Township, Taitung County	<b>Debris Number</b>	Taitung County DF097
<b>Drainage</b>	Coastal rivers in Taitung	<b>River</b>	Coastal tributaries in Daniao
<b>Rainfall threshold value for debris flow warning</b>	450 mm	<b>Disaster</b>	Stream debris flow
<b>River length</b>	2.418km	<b>Catchment area</b>	88 hectares
<b>Geology</b>	Palaeogene period metamorphic rock	<b>Slope</b>	30~50°
<b>Scale landslide in catchment area</b>	Large-scale landslide, landslide rate > 5%	<b>Downstream material accumulation</b>	The average size of debris flow stones between 3" ~ 12"
<b>Hazards</b>	Silting and burying, bumping	<b>Priority processing level</b>	High
<b>Facility</b>	Debris barrier, settling basin	<b>Coordinate  (TWD97)</b>	X coordinate : 240780
<b>Elevation</b>	190 m		Y coordinate : 2476727
<b>Protected object</b>	<b>Residential</b>	<b>Public building</b>	<b>Transportation facilities</b>
	5 or more	Yes (Daniao primary school)	Provincial highway 9
<b>Historical disaster</b>	Typhoon Morakot in August 2009.		
<b>Monitoring results</b>	1. In 2010, typhoon Namtheun (was merged by Lionrock) and typhoon Lionrock caused Daniao accumulated precipitation risen to the warning (9/2 18:51), but did not occur debris flow. 2. In 2010, typhoon Meranti caused Daniao accumulated		


precipitation risen to the warning (9/8 08:06), but did not occur debris flow.

3. In 2010, typhoon Fanapi caused Daniao accumulated precipitation risen to the warning (9/19 21:41) (9/19 21:41), but did not occur debris flow.
4. The extremely heavy rain on October 17, 2010 and typhoon Megi caused Daniao accumulated precipitation risen to the warning (10/22 13:16), but did not occur debris flow.
5. The extremely heavy rain on June 10, 2012. Daniao accumulated precipitation risen to the warning (06/14 14:13), but did not occur debris flow.
6. In 2012, typhoon Tembin caused Daniao accumulated precipitation risen to the warning (8/24 12:26), but did not occur debris flow.
7. In 2016, typhoon Nepartak occurred strong wind in Daniao.
  - (1) Steel wires (up and down) in debris barrier were fractured. (07/08)
  - (2) Steel wires (up and down) in settling basin were fractured at downstream. (07/08)
  - (3) Steel wires (up and down) were fractured at upstream in Daniao tribal creek. (07/08)
8. In 2016, typhoon Aere caused Daniao accumulated precipitation risen to the 450mm warning (10/09 05:29), but did not occur debris flow.
9. In August 23, 2018. Tropical Depression caused Daniao accumulated precipitation risen to the 450mm warning (08/30 02:23), but did not occur debris flow.

Note: Landslide rate= landslide in watershed area/watershed area

# Geographical position map

Basic topographic map



Three-dimensional map



# The instrument erection of Daniao station

Position map of instrument erection

## 大 鳥

**Daniao**  
Debris Flow Monitoring Station

450  
mm  
土石災害  
警戒雨量

450  
mm  
大雨警戒雨量  
警戒雨量

農業部農村發展及水土保持署  
Agency of Rural Development and Soil and Water Conservation, MOA

---

/// 土石流觀測站 ///

台東縣大武鄉大鳥村

**大鳥部落野溪** Daniao Tribe Creek

台東縣大鳥村自建處於溪墘溪溝尾 DF097 下方，自興建之初因溪溝狹窄，溪水暴漲，造成 15 萬立方公尺土石滑動，波及下游村莊約 250 戶民宅，計造成 5 戶房屋受損，幸無生命財產損失，道路損壞 120 公尺。民國 99 年凡那比颱風、梅姬颱風，民國 101 年 0610 莫蘭，在該處大鳥部落造成山崩，但無人員傷亡。

The landslide at Daniao Village was at the downstream of debris flow, Taikung DF097 Typhoon Merapi had caused 150,000 m<sup>3</sup> landslides, resulting in a rising river and threatening the lives and property of about 250 local residents. There were 5 houses were damaged and the broken road was about 120 m long. The Typhoon Fanapi and Meg in 2010, and the 0610 heavy rainfall in 2012 had through the Daniao Village abundant rain and the rainfall alert had been reached. However, no disaster had occurred during the events.

## Instrument description of Daniao station

Instrument name	Purpose	Quantity
CCTV	Monitoring the live situation of river, gather the information of real-time image on site.	4
Rain gauge	Measuring the local rainfall of monitoring station to be an important basis for release the debris flow warning.	2
Wire sensor	The impact of debris flow fractured the steel wire and send out the debris flow warning, which can obtain the time data of debris flow.	2
Geophone	Surface vibration caused by the rolling of debris flow is measured by the geophone. If the vibration frequency exceeds the warning value, the system will automatically sends the warning message.	2
Soil moisture meter	The soil moisture meter can record the water saturation of soil, provide the different soil and the relationship between moisture content with debris flow analysis	1

頁-4


	research.	
--	-----------	--

## Debris flow disaster report

# 98年莫拉克颱風重大土石災例最速報

98年莫拉克颱風

## 台東縣—大武鄉大鳥村



**98年莫拉克颱風-台東大武-002**

- 災害位置: 大武鄉大鳥村(台9線420.5k旁)
- 災害發生時間: 8月8日15時
- 災害類型: 土石流(東縣DF097與東縣DF098)
- 有效累積雨量: 951.0mm

災害描述與統計:

- 民宅大鳥346號等8戶, 以及無門牌鐵皮屋及竈櫃遭土石掩埋。
- 大鳥村聯外道路亦遭土石掩埋。
- 本次土石災害危害範圍甚廣, 所幸村長即時進行村民之疏散避難, 因此並無人員罹難。

註1: 坐標採TWD97系統  
註2: 降雨組體圖資料來源—水土保持局土石流防災資訊網



優質、效率、團隊

行政院農業委員會水土保持局